

35	32 S01	Rotary switch with marking "I-O-II" net1-off-net2 (change over switch with 0-position 3- pole)	3SB3 000-0DA1 3SB3 901-0AW 3SB3 400-0A	Siemens L&T (SALZER) TEKNIC/ GE/KAYCEE	S1S02 (RSW-1)
36	33 Q1	Motor protective relay water pump MBS 25, 1-1.6 A with aux. Contact HS9.11 and terminal block db	910-201-205 910-292-130 910-293-209 3RV1021 1AA10 +3RV 1901 1E	AEG L&T/Group schneider/ABB SIEMENS	S1F21
37	32 S07	Toggle switch 0-1 power supply on-off with socket and 2 NC	3SB3 000-2KA11 3SB3 901-0AC 3SB3 400-0D, 61006-S6-B19-400-FH-BB-OFF-ON	Siemens L&T (SALZER) TEKNIC SALZER	S1S01
38	32 S08	Rotary switch 3-pole, 2-way with OFF		Siemens SALZER Kaycee	
39	93 A1	item deleted			
40	93 F01	Fuse 5 x 20mm (fuse clamp at the X1.2) insulation control TZA	282-128/281-413(clamp)	Wago/Wickmann/ RS/Ferraz/Phoenix/ Weidmuller	S1A6 S1F58
41	93 F02	Fuse 5 x 20mm (fuse clamp at the X1.2) insulation control TZA	282-128/281-413(clamp)	Wago/Wickmann/ RS/Ferraz/Phoenix/ Weidmuller	S1F59
42	X1	Terminal block for High voltage Box			S1X1.1
43	33 K06	Auxiliary contactor SH5.31, DC110V with diode water pump 110V DC	SH5.31,DC110V TKC631-Z,110VDC GJH1213061R6312 3RH1131-BF40 3RT1916-1DG00	AEG ABB Siemens/L&T/ Schneider	S1K24
44	33 K07	Auxiliary contactor SH5.31, DC110V with diode water pump 110V DC	SH5.31,DC110V TKC631-Z,110VDC GJH1213061R6312 3RH1131-BF40 3RT1916-1DG00	AEG ABB Siemens/L&T/ Schneider	S1K25
REGULATED BATTERY CHARGER CUBICLE					
45	X3	Terminal block X3	Drawing no. LS70105	Wago/Phoenix/ Weidmuller	S1X3
ON-BOARD LV CUBICLE					
46		RCBO suitable for 10 amps , 30 mAmps		Siemens MDS/LeGrand	
47		Rotary switch panel for Non-AC coaches	CC72399	RDSO/RCF approved sources	
48		Rotary Switch for Mobile charging socket		Siemens SALZER Kaycee	
49		Rotary Switch for feeder changeover 16 Amps 6 way with off		Siemens SALZER Kaycee	
MISCELLANEOUS					
50		PVC alleys	L&T/AKG		
51		Halogen free electron beam irradiated cables of various sizes	RDSO specification no. ELRS/SPEC/ELC/0019, Rev-2	RDSO/RCF approved sources	
52		Multiple accessories like locks, hinges, handles etc.	Dirac/Hafele/equivalent imported make		
53		Computer Generated Ferrules	Tyco/Phoenix/Penduit		
54		Cable Jackers	PMA Jack,Fedral Mogul, Werner Hahn	PMA/ Fedral Mogul/ Werner Hahn	
		Note: 1. Inspecting agency will check all the components above and maintain record for future reference. No deviation in above will be acceptable. 2. Calibration certificate of measuring instruments i.e voltmeter,ammeter to be submitted during inspection. 3. Coloured heat shrinkable sleeves shall be provided as per phase for easy identification.			