



**Report ID:** GEM/GARPTS/26052026/0BPTAU10Y0TL

**Report Name:** Repairing/Replacement of plates and Refractory work of Bottom Ash Hopper and other works like as changing of roller, Rail guide of feed gate system of BAH during overhauling of Unit #4, 2x210 MW, BTPS, Parichha

**Generated By:** Subas Chandra Saroj , Energy Department Uttar Pradesh

**Generated On:** 26/05/2026

**Valid till:** 25/06/2026

### **GeM Availability Report and Past Transaction Summary**

GeM Availability Report and past transaction summary report is generated based on the specifications searched by the Buyer. The specification may be modified appropriately for searching relevant categories on GeM. Buyer may navigate to GeM category page by clicking on the category link to view category specifications and products/services available in the category.

*Order Count and Order Value displayed is on a cumulative basis since GeM inception.*

**1. Search String: Repairing/Replacement of plates and Refractory work of Bottom Ash Hopper and other works like as changing of roller, Rail guide of feed gate system of BAH during overhauling of Unit #4, 2x210 MW, BTPS, Parichha**

Search type: Product

Search Result: Category not available on GeM for the text string searched by the buyer.

This is a one-time requirement hence new category creation is not proposed / or requirement is recurring but request for new category creation will be submitted separately post generation of GeMARPTS.

Estimated Value Of Procurement: ₹ 1529960.0