

REGIONAL RESEARCH INSTITUTE FOR HOMOEOPATHY
Plot no. 38 & 39, Sector - 18 & 19, Kharghar, Navi Mumbai - 410 210
(Basement + Ground + 3 Floors)

Equipment Installed for Hydrant System.

Sr. No.	Description	Quantity	Remark
	<u>Hydrant System</u>		
1.	Total Riser	10	Present working status To be verified by Bidder before quoting financial BID
2.	Duct -1 Double Headed Hydrant Valve	05	Present working status To be verified by Bidder before quoting financial BID
3.	Duct -2 Single Headed Hydrant Valve	05	Present working status To be verified by Bidder before quoting financial BID
4.	Courtyard – Landing Valve	06	Present working status To be verified by Bidder before quoting financial BID
5.	4 way Fire Inlet Connection	01	Present working status To be verified by Bidder before quoting financial BID
6.	2 way Fire Inlet Connection	01	Present working status To be verified by Bidder before quoting financial BID
7.	Hose Reel with Shut Off Nozzle	05	Present working status To be verified by Bidder before quoting financial BID
8.	Single Door Hose Box	16	Present working status To be verified by Bidder before quoting financial BID
9.	Branch Pipe Nozzle	16	Present working status To be verified by Bidder before quoting financial BID
10.	Booster Pump	01	Present working status To be verified by Bidder before quoting financial BID
11.	Main Hydrant Pump	01	Present working status To be verified by Bidder before quoting financial BID
12.	Jockey Pump	02	Present working status To be verified by Bidder before quoting financial BID
13.	Stand By Pump	01	Present working status To be verified by Bidder before quoting financial BID
14.	Sprinkler Pump	01	Present working status To be verified by Bidder before quoting financial BID
15.	LOOP - 01		Present working status To be verified by Bidder before quoting financial BID
A.	Smoke Detector	89	Present working status To be verified by Bidder before quoting financial BID
B.	Manual Call Point	03	Present working status To be verified by Bidder before quoting financial BID
16.	LOOP - 02		Present working status To be verified by Bidder before quoting financial BID
A.	Smoke Detector	92	Present working status To be verified by Bidder before quoting financial BID

B.	Manual Call Point	02	Present working status To be verified by Bidder before quoting financial BID
C.	Sounder	01	Present working status To be verified by Bidder before quoting financial BID
17.	LOOP - 03		Present working status To be verified by Bidder before quoting financial BID
A.	Smoke Detector	81	Present working status To be verified by Bidder before quoting financial BID
B.	Tem	01	Present working status To be verified by Bidder before quoting financial BID
C.	Manual Call Point	02	Present working status To be verified by Bidder before quoting financial BID
D.	Sounder	02	Present working status To be verified by Bidder before quoting financial BID
18.	LOOP-04		Present working status To be verified by Bidder before quoting financial BID
A.	Smoke Detector	77	Present working status To be verified by Bidder before quoting financial BID
B.	Manual Call Point	03	Present working status To be verified by Bidder before quoting financial BID
C.	Sounder	02	Present working status To be verified by Bidder before quoting financial BID
19.	LOOP-05		Present working status To be verified by Bidder before quoting financial BID
E.	Smoke Detector	27	Present working status To be verified by Bidder before quoting financial BID
F.	Manual Call Point	02	Present working status To be verified by Bidder before quoting financial BID
G.	Sounder	02	Present working status To be verified by Bidder before quoting financial BID

Regional Research Institute for Homoeopathy
Plot No 38 & 39, Sector-18, Kharghar, Navi Mumbai